



UFI: NM30-E0RR-U006-MD6W
No. 19560700, thinner, 30 ml / 1.02 fl.oz.
Gefahr. Enthält: Butanon, 3-Pentanon.
Wiederholter Kontakt kann zu spröder
oder rissiger Haut führen.

die:master

30 ml

Renfert GmbH
Untere Giesswiesen 2
78247 Hilzingen/Germany
Tel. +49 7731 8208-0
www.renfert.com
Made in Germany

Renfert

217617 923E

Опасно. Содержит: Бутанон,
3-пентанон. Паспорт безопасно-
сти на русском языке Вы найдете
на сайте: www.renfert.com.

危險. 含: 丁酮, 戊-3 - 酮.

危険。 成分: ブタノン, 3-ペンタ
ン。

위험. 함유: 부탄온, 펜탄-3-원.

خطر. تحتوي على. بوتانون. بينتان - 3 -
واحد

Pericol. Contine: butanonă, pen-
tan-3-onă. Expunerea repetată
poate provoca uscarea sau crăpa-
rea pielii.

Opasnost. Sadrží: butanon, pen-
tan-3-on. Učestalo izlaganje može
prouzročiti sušenje ili pucanje
kože.

Danger. Contains: butanone, pentan-3-one. Repeated exposure may cause skin dryness or cracking.

Full labeling information is provided on the outside package. Refer to the Safety Data Sheet.

Danger. Contient : butanone, pentane-3-one. L'exposition répétée peut provoquer dessèchement ou gerçures de la peau.

Pericolo. Contiene: butanone, 3-pentanone. L'esposizione ripetuta può provocare secchezza e screpolature della pelle.

Peligro. Contiene: butanona, pentan-3-ona. La exposición repetida puede provocar sequedad o formación de grietas en la piel.

Perigo. Contém: butanona, pentan-3-ona. Pode provocar secura da pele ou fissuras, por exposição repetida.

Tehlikeler. İçerir: 2-Bütanon, Pentan-3-on. Tekrarlanan maruz kalmalarda deride kuruluğa ve çatlaklara neden olabilir.

1-50002016



No. 1956 0700
die:master
thinner



Renfert GmbH
Untere Giesswiesen 2
78247 Hilzingen/Germany
Tel. +49 7731 8208-0
www.renfert.com
Made in Germany

UFI: NM30-E0RR-U006-MD6W

Gefahr. Enthält: Butanon, 3-Pentanon

Danger. Contains: butanone, pentan-3-one

Renfert USA
3718 Illinois Avenue
St. Charles IL 60174
Toll Free (001) 800 336-7422